P 916

G. M. 1916

550 8 16.

Sl. No. 6.8.21.27

V. 44

Hill Stations.

G. R. S. IX-5]

Previous references.

1916-17

(Year Book)

File No. 550-16

Serial Nos. 6-8-21-27

Later references.

J. No: 550. 16.
8C: 517, 16, 19, 24,
6-8, 29, 31, 33.

GENERAL AND REVENUE SECRETARIAT.

Serial Nos. 3-8-21-27

Part B for May 1918

SUBJECT.

For order for sanction these estimates aggregate Rs 1,16,150/- for erection of the artistic effect of the Victoria memorial Hall Calcutta also for opening out a new cliff-cut road to the foot of the Dik

---

[illegible] Chief Secy's
Ord Dp. 15757 of 27-8-1918.
Vide [illegible] Rs. 28 that
[illegible] 1919-20 [illegible]
[illegible] Appropriation [illegible]

W D 89--GPB--50,000--24-7-16

191 .

GENERAL AND REVENUE SECRETARIAT.

NOTES.

File No.

File Heading.

No. Dated Received

Enclos Spare Copies. Serial No

Brief Abstract of Letter.

NOTES AND ORDERS.

Noted. for orders with a copy of the G.O. relating to improvements to Hill Stations.

Notes. First Sheet.

Q. No. 5/171

Subd. There is no provision in the Budget for Chamundi Hill improvements. It will have to be debited to the W. Deptt.

W.N. 18/5

+6

Draft Subd.
W.N.
7/6

Subd. 2. connection with the Scheme for pumping water to the Chamundi Hill, the Chief Engineer has been asked to state if [illegible] cannot be met from any of the sanctioned items in the D.W. budget.

K.N.
23/8

Ref - para 7.

G.S. [illegible]

Government Secretariat

G.M. File No. 530 of 1916.

Sub.

No.

Submitted with a copy of the order passed sanctioning the estimates for the water supply Scheme & for completing [illegible]

[illegible]

These works cannot be taken up this year for want of funds. May the Chief Engineer be requested to provide for these two works and also for [illegible] referred to in his Order under reference [illegible] in the Budget for 1918-19?

To Chairman with compliments & [illegible]

[illegible]

Returned with compliments, the intimation that provision has been made for Item Nos 1 and 2 in the draft Public Works Budget for 191 -19 in accordance with Government Proceedings No.C.3774-30/ G.O.500-15-20 dated the 13th January 1916.

for Chief Engineer of Mysore.

M.P.P.

Name Contn. sheet

Form No. 13]
General and Revenue
Department

File No. of 19

Serial No.

Items 1 + 2 referred to in G.O. '74 - 80 fin. 550-16-26 & 18-1-18 have provided for in the budget for 1918-19. na 17 of the notes above.]
in the items 3 + 4 refd. to in the said and the three items mentioned in should also be provided for is = for orders.

Ref. Para 17.
The items 1 + 2 referred to in G.O. No. S. 7774-80 fin. 550-16-26 & 18-1-18 have been provided for in the budget for 1918-19.
Of the items 3 + 4 and also the 3 items referred to in Sl. 3. should be taken in hand, the necessary provision will have to be made.

Perhaps the other items may be taken [illegible] budget

Yes.

JB 50,000 12-8-10

G. R. S. III-2]

General and Revenue Secretariat.

In the File No. 756 of 191/.

Serial No.	
	Subtd with a draft letter 14/5/18
97	To The Chief Engineer No 9 757 dt 21.5.18 Forwarded with map to the roads [illegible]

REV. SECT. V GENERAL 17 MAY 1918

NOTE—Contn. sheet.

WD A 1709—GPB—60,000—20-9-18—S.

9691

TELEGRAPHIC ADDRESS: Statewks.

No. 4456

MYSORE P. W. DEPARTMENT.

CENTRAL OFFICE,

Bangalore 28 *May* 191 7.

From Rajasabhabhushana
KARPUR SHRINIVASRAO, ESQ., B.SC., L.C.E.,
Chief Engineer of Mysore,
Bangalore.

To

B.Ramaswamayya, Esq., B.A., B.L.,
Offg. Secretary to Government, Revenue Department,
Bangalore.

Sir,

With reference to item No.8 of statement B accompanying Government Proceedings (P.W.) No.2051-7/10008-14 of the 23rd September 1916, I have the honour to forward, for favour of sanction, the marginally noted three estimates

1. Improving the artistic effect of the Chamundi Hill top	Rs 27,240
2. Acquiring all the houses on the platform on the top of the hill enclosed by the car road round the temple and providing sites for constructing houses for the displaced	16,600
3. Opening out an Elliptical road at the foot of the hill	2,310

Rs 46,150 for improving the artistic effect of the Chamundi Hill top received from the President, City Municipal Council, Mysore.

2. The reports attached to the estimates explain the details of the works proposed.

3. The President of the Mysore City Municipal Council has been requested to report the source from which the cost is to be met.

I have the honour to be,
Sir,
Your most obedient servant,

for Chief Engineer of Mysore

Re: [illegible] accompany the estimate for improving the artistic effect of the [illegible] vide item No. 8 of Memorandum sheet.

Ref: - Government Order No. 2051-7/P... 10008-14 dated 23rd October 1916.

The improvement of the top of the Hill consists chiefly of the following items of work.-

1. Dismantling the unsightly parapet round the Car road and rebuilding the same with perforated ornamental parapets of improved design. A lumpsum rate of Rs. 5 /- per running foot is provided in the estimate. The details of design of the parapet will be worked out while carrying out the work.

2. In front of Sri Narayanaswamy Temple there was a huge rock blasted several years ago and the blasted surface appears unsightly. It is now proposed to build up a brick masonry skin wall to cover up the broken surface.

3. At the South Eastern corner of the hill close to Sri Narayanaswamy Temple the ground is uneven and sloping. It is proposed to convert this into a level platform by revetting the outer edge. This is a very prominent corner of the Hill as it overlooks the Extension of Mysore known as the Industrial Suburb.

4. At 1/8 of CHAMUNDI HILL road, the road is narrow and steep and it is therefore proposed to widen the road by acquiring a few houses and reduce the steep gradient by blasting.

5. For a length of 416 feet from the hill top, there are no defined steps. The approach is rough and slippery [illegible]. It is proposed to make the level -

Estimate of the probable cost of Improving the Artistic View of the Chamundi Hill

Details of work	No.	Dimensions L	B	D	Contents	per Quantities
Eastern or front side	1	430	2¼	4½	4354	
Southern do	1	290	2¼	4½	2936	
Western or rear side	1	460	2¼	4½	4658	
Northern – do	1	240	2¼	4½	2430	
Add for curves & bits here & there		L.S.			100	
Total						Cft. 14478
Constructing face wall to cover the rough surface of the blasted rocks near Narayanswamy's temple	1	130	1⅛	8	1170	
Total						Cft 1170
Eastern wall	1	430			430	
Southern wall	1	290			290	
Western wall	1	580			580	
Northern wall	1	240			240	
Add for bits here & there		L.S.			160	
Total						Rft 1700
Coping over the parapet						
Eastern Side	1	430			430	
Southern Side	1	290			290	
Western Side	1	580			580	
Northern Side	1	240			240	
Total						Rft 1540

...nce on the both sides

Eastern side	1×2	430	860
Southern side	1×2	290	580
Western side	1×2	580	1160
Northern side	1×2	240	480
Total			Rft 3080

Eastern side of Sree Chamundeswari Temple	44	44
Southern side	30	30
Western side	59	59
Northern side	24	24
Total		Nos 157

Eastern side	2	2
Southern side leading to Uttanhalli	2	2
Western side towards Narayanswamy temple	2	2
Northern side	2	2
Northern side at entrance to Devekere.	2	2
Total		Nos 10

North of Shammudeswari Temple.	1	$\frac{30'}{3}$	$\frac{20'}{3}$	$\frac{1}{3}$	67	
On road from Bunglow in $\frac{3}{5}$ furlongs. Right side	1	20	2	$2\frac{1}{2}$	100	
Left side	1	20	3	$2\frac{1}{2}$	150	
Total						Cyd 317
Do		Lump Sum				Rs 1000
Do						Cyd 100
do		L.S				Rs 150
Do	2	416	$1\frac{1}{2}$	2	2496	
Total						Cft 2496
Do	180	10	$1\frac{1}{4}$		2250	
Do	130	10	$1\frac{1}{4}$		1625	
Do	66	10	$1\frac{1}{4}$		825	
Do	40	10	$1\frac{1}{4}$		500	
Total						Sqft 5200
Both sides of parapets	2×2	416	2		3328	
CO						3328

• Estimate of the probable cost of improving the Artistic View of the Chamundi Hill.

Details of work	No.	Dimensions L	B	D	Contents for quantities
Eastern or front side	1	430	2¼	4½	4354
Southern do	1	290	2¼	4½	2936
Western or rear side	1	460	2¼	4½	4658
Northern — do	1	240	2¼	4½	2430
Add for curves & bits here & there		L.S.			100
Total					Cft 14478
constructing face wall to cover the rough surface of the blasted rocks near Narayanswamy's temple	1	130	1⅛	8	1170
Total					Cft 1170
Eastern wall	1	430	.	.	430
Southern wall	1	290	.	.	290
Western wall	1	580	.	.	580
Northern wall	1	240	.	.	240
Add for bits here & there		L.S.			160
Total					Rft 1700
Eastern Side	1	430	.	.	430
Southern Side	1	290	.	.	290
Western Side	1	580	.	.	580
Northern Side	1	240	.	.	240
Total					Rft 1540

Abstract

Items	Per	Rate Rs as p	Quantity	Amount in Rs.
Dismantling masonary	Cft	9	14478	678
Burnt brick in mortar	Cft	8	1170	585
Constructing parapet wall with ornament & perforation, & Plastering on both Sides	Rft	5	1700	8500
Coping	Rft	8	1540	770
Cornice	Rft	8	3080	1540
Constructing Pillasters to parapet wall at intervals of 10 ft.	each	3	157	471
Constructing gate pillars with ornamental bases, plastering etc.	each	50	10	500
Blasting Rock	Cyd	4	317	1268
Earth work	Lump Sum			1000
Rough Stone work dry.	Cyd	2	100	200
Improvements to Steps; dismantling existing rough Stones	Lump Sum			150
Dressed Slabs for Steps.	Sqft	1	5200	5200
Rough Stone in Mortar	Cft	8	2496	1248
Cement Pointing	Sqr	5	74.88	375
Repairs to Narayanaswamy temple steps	Lump Sum			200
Constructing rough Stone revetment N. W Corner near Narayanaswamy temple	Cyd	2 8	147	368

C.D.

B.7

Earthwork for platforms	Cyds.	8.	1122		561
Gravelling and Sanding	Lump Sum				50
Providing Stone Seats + Benches	Lump Sum				100
Improving the approach road from temple to Devekkere	Lump Sum				1000
Total					2476
Contingencies at 5%					1238
Temporary Establishment Charges					1238
Grand Total				Rs	27244

I duly recommend

President

Recommended

Municipal Engineer

Report to accompany the estimate for opening out an Elliptical road at the foot of the Chamundi Hill step road.

The present road is very narrow and runs straight to the foot of the step road. It is very in-convenient for carriages and Motors to turn round as there are rough stone platforms on both sides. It is therefore proposed to open out an Elliptical road having a width varying from 20' to 40' , so as to give more space at centre for sidings of carriages and Motors.

2 . Two rugh stone culverts will be built at low level to discharge surface water.

3. The masonery culvert across the feeder chanel will be widened to 40 feet as mentioned in the plan.

4. A lumpsum provision of rupees 300/- is made for planting avenue trees on both sides of the proposed road as mentioned in plan.

Ishwara Rao

MRV. President.

Estimate of the probable Cost of opening the elliptical (now) at the foot of Chamundy Hill Mysore City

SECRETARY'S REGD. NO. 17 APR 1917 MYSORE P. W. DEPT.

Details of work	No.	Dimensions L	B	D	Cubic Contents	Quantity	Per	Rate Rs	a	p	Amount Rs
"Earthen embankment"											
Section A to B	1	50	$\frac{40+76}{2}$	3	5400						
B to C	1	50	$\frac{28+40}{2}$	5	8250						
C to D	1	50	$\frac{40+40}{2}$	4	8800						
D to E	1	50	$\frac{48+24}{2}$	2	4400						
E to F	1	20	$\frac{32+12}{2}$	1	760						
J to K	1	50	$\frac{12+32}{2}$	1	1850						
K to L	1	50	$\frac{32+32}{2}$	1	1350						
L to A or M	1	50	$\frac{32+48}{2}$	1	1600						
Total					32110	1189	Cyd	-	4	-	166
Deduct Spoil from cutting							"		6	"	197
Collecting blow sand & Setting aside for dressing	220	5	3/8		138	138	Cyd	1	10	-	220
Consolidation of Metal					138	138	Cyd	-	4	-	35
Collecting gravel (Lime nodules)					50	50	Cyd	-	8	-	25
Consolidation of gravel					50	50	Cyd	-	2	6	8
Sanding and Rolling	Lump Sum										10
Removing Rough Stone from Eastern side and reconstructing the same in a line	Not shown in plan										
Western Side	1	120	1/2	1/2	90						
	Lump Sum				60						
Total						120	Cyd	-	12	-	98
New Rough Stone dry work Constructing embankment over drain	1	70	1/2	2	70	Not shown					

764

Embankment over Culvert drain	200	10	½	1	20							
Do Lowering	2	10	½	⅓	7							
Total					97	97	Cft	1	8	-	146	
Burnt Stone slab 4" Covering	2	28	3	.	168	168	Sft	-	6	-	63	
Turfing slopes of Bund Av drain	2	600	2½	.	3000	30	Sqs	1	-	-	30	
Improving junctions	Lump Sum										50	
Improving drainage etc	Lump Sum										40	
Avenue plants and tree guards	Lump Sum										300	
Jungle clearing	Lump Sum										30	
Retaining tunnel.												
Brick in mortar												
Side walls and abutments foundation	4	20	1½	2	240							
" Superstructure	4	20	1½	6	560							
" Wings	4	15	1½	4	270							
Total						1050	Cft	-	3	6	830	
"Chunam plastering"												
Sidewalls and abutments	6	20	6	-	720							
Wings	4	15	4	-	240							
Faces	Lump Sum				40.							
Total					1000	10	Sqs	2	12	-	28	
Rave Covering Slab 6" thick	1	20	20	.	400	400	Sft	-	8	-	200	
Ornamental Parapet wall including Coping	2	40	.	.	80	80	Rft	3	-	-	240	
Other Unforseen items	Lump Sum										50	
											2170	
Total											~~2407~~ 118	
Contingencies @ 5%											~~106~~	
Temporary Establishment											106	
Grand Total											2360	
											~~2407~~	

(Sd) E. Ramaswamy Iyer
Municipal Engineer

"Copy"

Edirimanasinghe
14/4/1 Power of Attorney

E. Ramaswamy
Municipal Engineer

13/6

G. R. S. 26]

File No. 550-6

Serial No. 8

Diary No. of letter replied to.....

No.

General and Revenue Secretariat

( )

, the 191 .

Date of issue.....

Signed by.....

To

The ~~Chief~~ President,
City Municipal
Council, Mysore

Sir,

I am directed to forward the accompanying copy of letter no. 4456 B 2nd May 1917 ~~[illegible]~~ from the Chief Engineer requesting sanction to certain estimates for improving the artistic effect of the Chamundi Hill top and to request that the views of the Municipal Council ~~may kindly be obtained~~ referred to in para over 3

SUBJECT. of the said letter
~~May kindly be obtained~~

~~refund to the amount from which~~
~~cost is to be met~~) ~~and pointed~~ Mr Hunt's credentials are forwarded
an early date

2 Lavie etc

For Secy of State
Govt of India

is forwarded
Copy to the Chief
Engineer with reference
to his letter no 4456
dated 2 May 1917

7/6/17

List of enclosures

Copied by

Examined by

GPB—20,000—10-10-4

1429

No. 22

for 550-16

THE CITY MUNICIPAL OFFICE, MYSORE,
Dated 17th August *191* 7.

From

T. L. Lukshmana Rao, Esquire., L. C. E.,
President, City Municipal Council,
Mysore.

To

D.M. Narasinga Rao, Esquire., B.A., B.L.,
Secretary to the Govt. of Mysore,
General ~~*Revenue Department.*~~
Bangalore.

SIR,

With reference to your letter No. 16660/G1. 550-16-8 dated 13th June 1917 requesting that the views of the Municipal Council may be obtained for the sanction of certain estimates for improving the artistic effect of the CHAMUNDI HILL TOP, I have the honour to state that as the Hill is outside the Municipal Limits, the Municipal Council cannot deel with this question.

2. The expenditure ought to be met from the General Revenues/and District Funds.

I have the honour to be,

Sir,
Your most obedient servant,
T Lukshmana Rao
President.

MRV.

191

REVENUE & REV. SECRETARIAT V GENERAL 1917

From

The President, City Muni. Council, Mysore.

To

The Secy. to Govt. of Mysore, General ~~Rev.~~ Dept. Bangalore

Dated 17th ~~July~~ Aug/17.

Despatched

Received

General No. 22

No.

Enclosure No.

Stating that the Channarayapatna Town is outside the Muni. limits the Muni. Council cannot deal with the question of Drinking

G. R. S. VI—G/32]

SUBJECT.....

.....

.....

Diary No. of letter replied to.....

GENERAL AND REVENUE SECRETARIAT,

( )

, the *191*

Date of issue.....

Signed by.....

Section

File No.

Serial No. 2

No.

To

The Chief Engineer of Mysore

Sir,

With reference to the correspondence ending with your unofficial Note No. 28 of 9.3.18 stating that provision has been made in the Rev. & Irrigation Budget for 1918-19 for improvements to the Chamundi Hill in accordance with Go. No. G.9774-80 / G.M.550-16-20 of 18.1.1918, I am directed to state that other improvements to that hill may be taken up in the year 1919-20 unless

over.

(D mere found can be found
, appropriation in the P.W.D
y.t.

I have

List of enclosure

Copied by

Examined by

W.D 86—G.P.B—60,000—15-11 16

Statement of Lines proposed
to be acquired on the Cleveland side
of approach to the Temple and the
cost of acquiring the same.

1		Gollar Venkataramanaih	Land	13	20	29		Syd	0
			Tiled house ordinary				3	Aud	25
			Sundry Charges				Lump Sum		
2	1	Angadi Ranga	Land	13	20	29		Syd	0
			Tiled house ordinary				3	Aud	25
			Sundry Charges				Lump Sum.		
32 3	1	Chamaiah	Land	13	20	29		Syd	0
			Tiled house				3	Aud	25
			Sundry Charges				Lump Sum		
33									
4	1	Veerabhadraiyya	Land	15	10	25 22 78		Syd	
			Tiled house				6	Aud	30
			Sundry Charges				Lump Sum		
34 5	1	Padadagudi Veerappa	Land	25	15	42		Syd	
			Tiled House				6	Aud	30
			Varandah				6	Aud	2
35			Sundry Charges				Lump Sum.		
6	1	Betta	Land	14	10	16		Syd	0
			Tiled house				2½	Aud	20

0	7	4	0					
0	75	0	0					
2	12	0	85	Parapet wall	Road	open land	Ranges house	
4	0	7	4	0				
0	0	75	0	0			House of Gollar	
2	12	0	85	Parapet wall	Road	Venkataraman	Chamacho house	
4	0	7	4	0				
0	0	75	0	0				
2	12	0	85	Parapet wall	Road	Angadi Ranges house	open Land	R
4	0	19	8	0				
0	0	180	0	0				
5	8	0	205	Road and mantap	Chendra Sekara Subbanna's House	Palace Ridad and mantap.	Lane	
4	0	10	8	0				
0	0	180	0	0				
0	0	120	0	0				
5	8	0	316	Road	Mari Subba-nna's house	Lane	Mari Subbanna's open land	
4	0	4	0	0				
0	0	50	0	0				

77

			Sundry Charges	Lump Sum					
7	1	Hoofapa Subbanna	Land	18 8 14	40 26 12	122	Sud	0	
			Tiled House				6. Ank	40	
			Sundry Charges	Lump Sum.					
8	1	Chandra Sekara Subbanna	Land	30	70	233	Sud	0	
			Tiled house				25 Ank	30	
			Verandah				5 Ank	25	
			Sundry Charges	Lump Sum.					
9	1	Pandita Gundapa	Land	35	30	117	Sud	0	4
			Tiled house				15 Ank	30	
			Verandah				2 Ank	20	
			Pial - do -				3 Ank	20	
			Sundry Charges	Lump Sum					
10		Malalvadi Channana (Subbanna)	Land	50	44	2444	Sud	0	
			Tiled house				10 Ank	30	
			Verandah				5 Ank	10	
			Pial - do.				4 Ank	5	
			Side Veranda				5 Ank	10	
			Sundry Charges	Lump Sum.					
11		Pundu Subbanna. (owner)	Land	70 8	35 38	306	Sud	0	
		Channabasavanni	Tiled house				10 Ank	30	
		Nanjamma (Mortgagee)	Verandah				5 Ank	10	
			Entrance - do.				1 Ank	5	
			Sundry Charges						

770

					mari Subbais	mari -	
1	0	0	55	Road	open land	Subbenais o.p.l.	Road
				Padada Veera -			
0	30	8	0	bhadrafis house			
0	240	0	0	road, Bettas			
							Shed of Simha
4	8	0	275	House	Lane	Lane	Vahana
0	58	4	0	Palace Bidadi	Malalvadi		
0	750	0	0	Veerabhadrafis	Channamis	Archikas	Lane and
0	125	0	0	house	House	House	Panditeu
							Gundafis house
16	12	0	950	Lane			
0	29	4	0				
0	450	0	0				
0	40	0	0				
						Chendra -	
0	60	0	0	mari Subbais house		Sekar Subba	Shed of Simha-2
						mais House	Vahana
0	12	0	580		Lane	& Lane	
4	0	61	0	0			
0	0	300	0	0			
0	0	50	0	0	Chendra Sekara -		
0	0	20	0	0	Subbannais	Govt	Lane and
							Channabasava -
0	0	50	0	0	House	open land	Lane mais, Nanjafa -
	9	0	0	490			mais house
4	0	76	8	0			
0	0	300	0	0	[illegible]	Oddapada	Lane and Lane and
0	0	50	0	0	[illegible]	Nanjafis	Malalvadi Chalure mais
0	0	5	0	0	[illegible]	Channamis	House
	8	8	0	440	Lane	House	

1566

12	Chalura Etta	Land	52	38	220		Syd	0	
		House is dila-							
		pidated state				18	Ank	10	
		Sundry charges		Lump Sum					
13	Deepada Nanjappa	Land	18 8	80 40	196		Syd	0	
		Tiled house				12	Ank	30	
		Sundry charges		Lump Sum					
14	Hithappana Subbanna	Land	21	80	187		Syd	0	
		Tiled house				5	Ank	25	
		Dilapidated -do-				2	Ank	15	
		Verandah				7	Ank	10	0
		-do- Small				1	Ank	10	0
		Sundry charges							
15	Goramma wife of Ramanaiyya	Land	65	50	361		Syd	0	
		House is dila-							
		pidated condition				20	Ank	10	0
		Sundry Charges		Lump Sum					
16	Gopalayya and Almalamma	Land	70 16	35 15	299		Syd	0	
		Tiled House				31	Ank	30	
		Verandah				3	Ank	10	
		Rear house				6	Ank	20	0
		Out side pial							
		Verandah				3	Ank	5	
		Sundry Charges		Lump Sum					
17	Chami Temple Servant	Land	24 10	12 8	41		Syd	0	
		Tiled House				3	Ank	20	
		Verandah				1	Ank	20	

0	55	0	0			Channabasa-	Channa-		
0						vanna's	Basavanna's		
0	180	0	0			nanjanna's			
0	5	0	0	240	Lane.	House	nanjanna's House.	Lane	
0									
0	49	0	0		Channabasavana Nanjamma's House	Hithappana Subbanna's House	Govt. open Land	Lane	
	360	0	0						
	21	0	0	430					
0									
0	46	12	0						
0	125	0	0						
	30	0	0						
	70	0	0		Deepada Subba-	Goramma's	Govt.		
	10	0	0		nas House	house & Lane	open Land	Lane	
	18	4	0	300					
0	90	4	0						
					Hithappana				
	200	0	0		Subbanna's		Govt. open	Gopalayya	
	9	12	0	300	house & Lane	Road	Land	and Almalamma's House	
	74	12	0						
	930	0	0						
	30	0	0						
	120	0	0				Gowramma wife of Ramayya's		
	15	0	0						
	10	4	0	1180	Lane	Road	house	Lane	
	10	4	0						
	60	0	0						
	20	0	0						
				6016					

		Pial - do.					3	Anh	12	
		Sundry Charges	Lump Sum							
18	Rama Devarmutt	Land	30	12	40			Syd	0	
		Tiled house					5	Anh	30	
		Verandah					5	Anh	10	
		Sundry Charges	Lump Sum							
19	Mohari Chama	Land	12	15	20			Syd	0	
		Tiled house					3	Anh	30	
		Pial Verandah					3	Anh	19	
		Sundry Charges	Lump Sum.							
20	Mohari Deva	Land	18 10	28 10	67			Syd	0	
		Tiled house					6	Anh	30	
		Verandah					1	Anh	20	
		Sundry Charges	Lump Sum.							
21	Sotada Mancha	Land	18	20	40			Syd	0	
		Tiled house					2	Anh	25	
		Verandah					2	Anh	10	
		Pial - do.					2	Anh	8	
		Sundry Charges	Lump Sum.							
22	Davare Subbayya	Land	30	46	153			Syd	0	
		Tiled house					16	Anh	25	
		Verandah					2	Anh	15	
		Pial - do.					3	Anh	8	
		Sundry Charges	Lump Sum.							

					6016				
0	0	30	0	0			Ramadeva	open yard	
0		9	12	0	130	Road	mutta	of mahabala-Iswara Temple	Road
	0	10	0	0			open yard	open yard	
	0	150	0	0		Temple	of mahabala-	of mahabala-	
0	0	50	0	0		Servant-	Iswara Temple	Iswara	
		10	0	0	220	Chamir House		Temple	Lane
0									
0	0	5	0	0					
	0	90	0	0					
0									
	0	30	0	0		Road	mohari Dera		
		5	0	0	130		House	Lane	Road
0	0	16	12	0		mohari		open yard	
	0	180	0	0		Chamir House		of mahaba-	
	0	20	0	0		and Road	Lane	Iswara Temple	Road
		3	4	0	220				
4	0	10	0	0					
0	0	50	0	0					
0	0	20	0	0		mohari		open yard	
0	0	16	0	0		Dewa's house		of mahabala-	
		14	0	0	110	and Road	Lane	Iswara Temple	Road
4	0	38	4	0		open yard		open yard	
0	0	400	0	0		of mahabala-	Mallana	of mahabala-	
0	0	30	0	0		Iswara Temple	Dewa's house	Iswara	
0	0	24	0	0				Temple	Road
		7	12	0	500	"	"	"	"

7926

23	Mallana Deva	Land	15	32	54		Syd	0	
		Tiled house				3	Ank	25	
		Verandah				3	Ank	10	
		Sundry Chargs.	Lump. Sum.						
24	Kattige Chama	Land	15	32	54		Syd	0	
		Tiled House				4	Ank	25	
		Verandah				1	Ank	20	
		Sundry Chargs.	Lump Sum.						
25	Lings (owner) mortgaged to Kalaya	Land	15	32	54		Syd	0	
		Tiled house				3	Ank	30	0
		Verandah				1	Ank	15	0
		Sundry Charges	Lump Sum						
26.	Vobalamma do	Land	15	32	54		Syd	0	4
		Tiled house				4	Ank	30	
		Veranda				4	Ank	8	
		Ceiling	Lump Sum						
		Sundry charg	Lump Sum.						
27	Hombala wife of voda Deva	Land	44	20	98		Syd	0	
28	Hoova Pattre Manja- sepa	Land	20	36	80		Syd	0	
29	Pichel Deva (owner) mortgaged to Venkala -pailu.	Land	30	40	133		Syd	0	
		Tiled house				10	Ank	45	

				7326				
0	13	8	0					
0	75	0	0				open Yard	
0	30	0	0		Davane Subba	Kattige	J. mahabala.	
	1	8	0	120	Jogi's house	Chanai's House	Iswara Temple	Road.
0	13	8	0				open yard	
0	100	0	0		Mallana		J mahaba.	
0	20	0	0		Devi's	Linga's	Iswara	
	1	8	0	135	house	house	Temple	Road
0	13	8	0					
0	90	0	0		Kattiga	Vobala-	Pittel	
0	15	0	0		Chanai's	mnai's	Devi's	
	1	8	0	120	house	house	House	Road.
0	13	8	0					
0	120	0	0					
0	32	0	0					
	15	0	0		Linga's	Honnabale's	Pittel	
	4	8	0	185	House	Land	Devi's Hanu	Road
					Vobalanai's		Manjappa	
0	24	8	0	25	house	Road	Land	Road
0	20	0	0	20	Pittel Devi's House	Road	open yard Mahabala's -wara Temple	Honnabalesdas
0	33	4	0		Open Yard	Hoo patre	open yard	Linganna
0	450	0	0		J mahabales -wara Temple	Manjappa's Vacant Land	J mahaba Iswara Temple	Vobalanna's House
				7931				

3										
43.	Chambara Dikshitulu	Vacant land Sundries	8	30	27		Syd	0	4
44.	Marasi Devanna and Deepada - Chamundi	Vacant land Sundries	10	36	40		Syd	0	4
3										
45	Mari Subbanna	Vacant land Sundries	10	30	33		Syd	0	4
3										
46	Kodi puttanna	Vacant land Sundries	$\frac{8 \times 88}{2}$		39		Syd	0	4
3 Survey No 47 66	Land to be acquired for Construction of New houses									
	(1) Subbanna Son of Chandra Sekariah (2) Chamundi Son of Pandu Subbanna	Survey No 64	50 yds	88 yds	4400		Area	100	0
Survey No 48 65	(1) Varane Subba (2) Kunta Chama (3) Deva Son of Kunta Linga	Survey No 65 Sundries	44	42	130	120 / 17468	Area	100	0

12848

0	6	12	0				Maraide-	
	0	4	0	7	open land	Road	vanna's land	Land
0	10	0	0				Kari Subb	open land of Open Land
	0	4	0	10	open land	Road	anna's land	Kari Subbiah
0	8	4	0				Kodi pulla	Muni Devan
	0	12	0	9	open land	Road	nna's land	nna's land
0	9	12	0					
	0	4	0	10	open land	Road	open field	Kari Subbiah Land
0	90	14	7		Survey No 65	Village Boundary	Remaining Portion of Survey No 64 & Village	Survey No 65
0	360	7	11		Survey No	Survey No	Survey No	Remaining portion
	8	9	6	460	61 and 62	64 and Village	63	of Survey No 65

13364

[illegible]	13344
@ 15%	2000
Ground @ 10%	1256
Total	16600

I Ishaka Murana Rao
President
City Municipal Council
Nellore